

**Central Reclamation Phase III**  
**Continuous Noise Monitoring Result - City Hall**

Weather Condition:

Date	Time	5-Minute Measurements		
		Leq	L10	L90
30-Jun-07	00:01	52.7	53	52
30-Jun-07	00:06	52.8	53.5	52
30-Jun-07	00:11	53.4	54	52.5
30-Jun-07	00:16	52.9	53.5	52
30-Jun-07	00:21	52.8	53	52
30-Jun-07	00:26	52.9	53	52
30-Jun-07	00:31	53.3	54	52
30-Jun-07	00:36	52.4	53	51.5
30-Jun-07	00:41	52.6	53	51.5
30-Jun-07	00:46	53.7	55	52
30-Jun-07	00:51	52.9	53.5	52
30-Jun-07	00:56	53.7	55.5	52
30-Jun-07	01:01	53.2	54	52
30-Jun-07	01:06	53.3	54	52
30-Jun-07	01:11	56.2	59.5	52.5
30-Jun-07	01:16	54.6	57.5	52
30-Jun-07	01:21	55.1	57.5	53
30-Jun-07	01:26	62.3	64.5	56.5
30-Jun-07	01:31	59	61.5	56
30-Jun-07	01:36	54.7	55.5	54
30-Jun-07	01:41	53.7	54	53
30-Jun-07	01:46	53.1	53.5	52.5
30-Jun-07	01:51	52.8	53	52
30-Jun-07	01:56	52.7	53.5	52
30-Jun-07	02:01	52.5	53	51.5
30-Jun-07	02:06	52.7	53	52
30-Jun-07	02:11	54.1	55	52.5
30-Jun-07	02:16	53	53.5	52
30-Jun-07	02:21	52.7	53	52
30-Jun-07	02:26	53.1	54.5	52
30-Jun-07	02:31	52.4	53	51.5
30-Jun-07	02:36	53.5	55	52
30-Jun-07	02:41	52.6	53	52
30-Jun-07	02:46	52	52.5	51.5
30-Jun-07	02:51	51.8	52	51
30-Jun-07	02:56	51.5	51.5	50.5
30-Jun-07	03:01	51.4	51.5	50.5
30-Jun-07	03:06	51.4	51.5	50.5
30-Jun-07	03:11	51.4	51.5	51
30-Jun-07	03:16	54.4	58.5	51
30-Jun-07	03:21	52.1	53	51
30-Jun-07	03:26	51.2	51.5	50.5
30-Jun-07	03:31	53.7	55.5	51.5
30-Jun-07	03:36	51.5	52	50.5
30-Jun-07	03:41	51.5	52	50.5
30-Jun-07	03:46	58.9	61.5	52.5
30-Jun-07	03:51	52.2	52.5	51.5
30-Jun-07	03:56	52.4	53	51.5
30-Jun-07	04:01	52.2	52.5	51.5
30-Jun-07	04:06	52	52.5	51
30-Jun-07	04:11	51.9	52.5	51
30-Jun-07	04:16	52.2	53	51
30-Jun-07	04:21	51.6	52.5	50.5
30-Jun-07	04:26	52.1	52.5	50.5
30-Jun-07	04:31	51.6	52	51
30-Jun-07	04:36	53.3	53.5	50.5
30-Jun-07	04:41	51.5	52	50.5
30-Jun-07	04:46	52.7	54	51
30-Jun-07	04:51	53.1	55	51
30-Jun-07	04:56	55.3	58.5	51.5
30-Jun-07	05:01	53.3	54.5	52
30-Jun-07	05:06	52.4	53.5	51.5
30-Jun-07	05:11	51.8	52.5	51
30-Jun-07	05:16	53.2	55	51.5
30-Jun-07	05:21	51.9	52.5	51
30-Jun-07	05:26	53.5	55.5	51.5
30-Jun-07	05:31	53	54	52
30-Jun-07	05:36	53.5	54.5	52.5
30-Jun-07	05:41	54.3	55.5	52.5
30-Jun-07	05:46	54.7	56	52.5

30-Minute Measurements		
Date	Time	Leq
30-Jun-07	00:26	53.0
30-Jun-07	00:56	54.5
30-Jun-07	01:26	57.6
30-Jun-07	01:56	53.0
30-Jun-07	02:26	52.6
30-Jun-07	02:56	52.2
30-Jun-07	03:26	54.2
30-Jun-07	03:56	52.1
30-Jun-07	04:26	52.4
30-Jun-07	04:56	53.2
30-Jun-07	05:26	53.9
30-Jun-07	05:56	58.8
30-Jun-07	06:26	55.9
30-Jun-07	06:56	63.2
30-Jun-07	07:26	64.7
30-Jun-07	07:56	65.0
30-Jun-07	08:26	65.9
30-Jun-07	08:56	66.3
30-Jun-07	09:26	69.4
30-Jun-07	09:56	64.4
30-Jun-07	10:26	65.7
30-Jun-07	10:56	70.2
30-Jun-07	11:26	67.5
30-Jun-07	11:56	64.6
30-Jun-07	12:26	67.2
30-Jun-07	12:56	69.2
30-Jun-07	13:26	68.9
30-Jun-07	13:56	69.0
30-Jun-07	14:26	66.6
30-Jun-07	14:56	63.9
30-Jun-07	15:26	66.3
30-Jun-07	15:56	67.9
30-Jun-07	16:26	68.4
30-Jun-07	16:56	67.0
30-Jun-07	17:26	66.3
30-Jun-07	17:56	62.8
30-Jun-07	18:26	65.8
30-Jun-07	18:56	65.9
30-Jun-07	19:26	<b>80.3</b>
30-Jun-07	19:56	<b>78.2</b>
30-Jun-07	20:26	<b>79.7</b>
30-Jun-07	20:56	<b>81.2</b>
30-Jun-07	21:26	<b>82.7</b>
30-Jun-07	21:56	<b>83.7</b>
30-Jun-07	22:26	<b>79.5</b>
30-Jun-07	22:56	63.6
30-Jun-07	23:26	60.1
30-Jun-07	23:56	57.3

Date	Time	5-Minute Measurements		
		Leq	L10	L90
30-Jun-07	05:51	54.4	55	53.5
30-Jun-07	05:56	53.7	54.5	52.5
30-Jun-07	06:01	57.2	59.5	54
30-Jun-07	06:06	64	67	58.5
30-Jun-07	06:11	57.6	59.5	55.5
30-Jun-07	06:16	56.6	58.5	54.5
30-Jun-07	06:21	54.5	55	53.5
30-Jun-07	06:26	54.5	55	53.5
30-Jun-07	06:31	55.1	55.5	54
30-Jun-07	06:36	58.1	61	54.5
30-Jun-07	06:41	54.5	55	53.5
30-Jun-07	06:46	56.1	58.5	54
30-Jun-07	06:51	55.7	57	54
30-Jun-07	06:56	56.1	57	54.5
30-Jun-07	07:01	61.7	64.5	57
30-Jun-07	07:06	64.7	66	62.5
30-Jun-07	07:11	63.5	65	60.5
30-Jun-07	07:16	64.1	66	61
30-Jun-07	07:21	64.6	66.5	61.5
30-Jun-07	07:26	62.2	64.5	58
30-Jun-07	07:31	64.5	66.5	61.5
30-Jun-07	07:36	65.1	67	61
30-Jun-07	07:41	65.4	67	62
30-Jun-07	07:46	65.2	67	61
30-Jun-07	07:51	65.2	67	60.5
30-Jun-07	07:56	62.5	65	58.5
30-Jun-07	08:01	63.2	65.5	59.5
30-Jun-07	08:06	64.6	66	62
30-Jun-07	08:11	66.6	68.5	63.5
30-Jun-07	08:16	65.1	67	60
30-Jun-07	08:21	66.4	68	64
30-Jun-07	08:26	67.4	69	64.5
30-Jun-07	08:31	66.2	66.5	64.5
30-Jun-07	08:36	66.9	68	65.5
30-Jun-07	08:41	65.8	67	63.5
30-Jun-07	08:46	64.9	66	62.5
30-Jun-07	08:51	62.8	64.5	58.5
30-Jun-07	08:56	64	68	58
30-Jun-07	09:01	62.8	65.5	60
30-Jun-07	09:06	64.3	65	62.5
30-Jun-07	09:11	66.8	68.5	64.5
30-Jun-07	09:16	68.1	70.5	64
30-Jun-07	09:21	68.7	71	65
30-Jun-07	09:26	69.9	71.5	66.5
30-Jun-07	09:31	70.4	72.5	66.5
30-Jun-07	09:36	69.4	72	65.5
30-Jun-07	09:41	72.4	77	64.5
30-Jun-07	09:46	64.2	65.5	62
30-Jun-07	09:51	64.4	65.5	62
30-Jun-07	09:56	65.4	67	62.5
30-Jun-07	10:01	65.7	67	63.5
30-Jun-07	10:06	64.9	66	62.5
30-Jun-07	10:11	63.7	65.5	61
30-Jun-07	10:16	64	65	60
30-Jun-07	10:21	61.7	63	60.5
30-Jun-07	10:26	65.3	67	61
30-Jun-07	10:31	64.4	66.5	61
30-Jun-07	10:36	66.3	67.5	64
30-Jun-07	10:41	65.1	66.5	63
30-Jun-07	10:46	66.9	68.5	63.5
30-Jun-07	10:51	66	67.5	63.5
30-Jun-07	10:56	66.5	68	64
30-Jun-07	11:01	67.1	69	64
30-Jun-07	11:06	74.2	78.5	68
30-Jun-07	11:11	67.8	70	65
30-Jun-07	11:16	68	68.5	64
30-Jun-07	11:21	71.5	73	63.5
30-Jun-07	11:26	71.7	72.5	64
30-Jun-07	11:31	66.3	68	63.5
30-Jun-07	11:36	64.8	66	63
30-Jun-07	11:41	66.5	68	63.5
30-Jun-07	11:46	65.1	67	62
30-Jun-07	11:51	65.9	67	64
30-Jun-07	11:56	65.3	67	60
30-Jun-07	12:01	63.8	66	59.5

30-Minute Measurements		
Date	Time	Leq

Date	Time	5-Minute Measurements		
		Leq	L10	L90
30-Jun-07	12:06	61.5	63.5	60
30-Jun-07	12:11	65.7	67	64
30-Jun-07	12:16	65.6	67	63.5
30-Jun-07	12:21	64.5	66	63
30-Jun-07	12:26	66.6	68	65
30-Jun-07	12:31	66	67	64.5
30-Jun-07	12:36	67.3	68	65.5
30-Jun-07	12:41	66.9	68	65
30-Jun-07	12:46	66	67	64.5
30-Jun-07	12:51	69.5	71	66.5
30-Jun-07	12:56	71.4	73.5	67
30-Jun-07	13:01	68.6	69.5	67.5
30-Jun-07	13:06	68.4	69	67.5
30-Jun-07	13:11	69.1	71.5	67.5
30-Jun-07	13:16	69.3	71	66
30-Jun-07	13:21	66.9	67.5	65.5
30-Jun-07	13:26	67.4	69	63.5
30-Jun-07	13:31	63.8	65	62
30-Jun-07	13:36	69.9	73.5	63
30-Jun-07	13:41	69	70	67
30-Jun-07	13:46	68.9	70	67.5
30-Jun-07	13:51	71.1	72.5	69
30-Jun-07	13:56	70.2	71.5	68.5
30-Jun-07	14:01	69.2	69.5	68
30-Jun-07	14:06	69.8	70.5	68.5
30-Jun-07	14:11	68.5	69.5	67
30-Jun-07	14:16	68.1	69.5	66
30-Jun-07	14:21	67.6	69.5	65.5
30-Jun-07	14:26	66.9	69	64.5
30-Jun-07	14:31	67	68.5	65
30-Jun-07	14:36	67.5	68.5	65.5
30-Jun-07	14:41	67	68	66
30-Jun-07	14:46	66.2	67.5	62.5
30-Jun-07	14:51	64.1	66	61.5
30-Jun-07	14:56	64	66	61.5
30-Jun-07	15:01	63.4	65	60.5
30-Jun-07	15:06	62.4	63.5	60.5
30-Jun-07	15:11	63	64.5	61
30-Jun-07	15:16	66.4	68	63
30-Jun-07	15:21	62.6	64.5	59
30-Jun-07	15:26	64.8	66.5	60.5
30-Jun-07	15:31	67	68	64
30-Jun-07	15:36	68.8	68.5	65
30-Jun-07	15:41	64.6	66	63
30-Jun-07	15:46	66.3	67	63
30-Jun-07	15:51	64.4	65.5	63
30-Jun-07	15:56	65.6	67	64
30-Jun-07	16:01	66.9	68	65
30-Jun-07	16:06	66	67	64
30-Jun-07	16:11	68.3	70	66
30-Jun-07	16:16	70.3	71.5	68.5
30-Jun-07	16:21	68.5	69.5	66
30-Jun-07	16:26	65.9	67	64.5
30-Jun-07	16:31	65	66	64
30-Jun-07	16:36	69.2	71	64
30-Jun-07	16:41	70.3	71	66.5
30-Jun-07	16:46	69.6	73	64
30-Jun-07	16:51	68.1	70.5	64.5
30-Jun-07	16:56	65.3	67	62.5
30-Jun-07	17:01	67.3	70	62.5
30-Jun-07	17:06	69.6	72	64.5
30-Jun-07	17:11	66.3	68	63
30-Jun-07	17:16	65.5	67.5	62
30-Jun-07	17:21	66.4	68	64
30-Jun-07	17:26	66.2	69.5	62
30-Jun-07	17:31	63	66	59
30-Jun-07	17:36	67.3	68.5	63
30-Jun-07	17:41	67.3	68.5	63.5
30-Jun-07	17:46	68.3	70.5	65.5
30-Jun-07	17:51	63.3	66	59.5
30-Jun-07	17:56	61.9	64	59
30-Jun-07	18:01	63.6	65	60.5
30-Jun-07	18:06	63.3	65	60.5
30-Jun-07	18:11	63	65	60
30-Jun-07	18:16	61.1	62.5	59

30-Minute Measurements		
Date	Time	Leq

Date	Time	5-Minute Measurements		
		Leq	L10	L90
30-Jun-07	18:21	63.5	65	60
30-Jun-07	18:26	64.2	66	61
30-Jun-07	18:31	64.8	67	61
30-Jun-07	18:36	68.7	72.5	63.5
30-Jun-07	18:41	65.8	67	63.5
30-Jun-07	18:46	64.6	67	60.5
30-Jun-07	18:51	65.1	67	61.5
30-Jun-07	18:56	66.2	68	63.5
30-Jun-07	19:01	65.1	67.5	61
30-Jun-07	19:06	65	67	61
30-Jun-07	19:11	66.4	68	63.5
30-Jun-07	19:16	65.6	67	63
30-Jun-07	19:21	66.8	69.5	63.5
30-Jun-07	19:26	70.1	74.5	63
30-Jun-07	19:31	73.3	78.5	61.5
30-Jun-07	19:36	<b>83.4</b>	86.5	76
30-Jun-07	19:41	<b>81.3</b>	85.5	65.5
30-Jun-07	19:46	<b>81.3</b>	85	65
30-Jun-07	19:51	<b>80.7</b>	83.5	70
30-Jun-07	19:56	<b>80.2</b>	82.5	69
30-Jun-07	20:01	<b>76.7</b>	81	59.5
30-Jun-07	20:06	71.2	75	61
30-Jun-07	20:11	74.3	77.5	62
30-Jun-07	20:16	<b>80.4</b>	83	69
30-Jun-07	20:21	<b>79.9</b>	82.5	68
30-Jun-07	20:26	<b>80</b>	83	66
30-Jun-07	20:31	<b>80.4</b>	82.5	75.5
30-Jun-07	20:36	68.4	70.5	64
30-Jun-07	20:41	73.2	76.5	63.5
30-Jun-07	20:46	<b>81.3</b>	83.5	74
30-Jun-07	20:51	<b>82.6</b>	84	80
30-Jun-07	20:56	<b>82</b>	84	76
30-Jun-07	21:01	<b>80.8</b>	83	75
30-Jun-07	21:06	<b>81.2</b>	83.5	61.5
30-Jun-07	21:11	74.5	78.5	61.5
30-Jun-07	21:16	<b>82.4</b>	86.5	63
30-Jun-07	21:21	<b>82.4</b>	85.5	72.5
30-Jun-07	21:26	<b>82.4</b>	85.5	70.5
30-Jun-07	21:31	<b>83.7</b>	86.5	69
30-Jun-07	21:36	<b>84.1</b>	87.5	66
30-Jun-07	21:41	<b>77.5</b>	81.5	61.5
30-Jun-07	21:46	<b>82.9</b>	85.5	67
30-Jun-07	21:51	<b>82.8</b>	84.5	80
30-Jun-07	21:56	<b>82.9</b>	84.5	79.5
30-Jun-07	22:01	<b>79.2</b>	83.5	59
30-Jun-07	22:06	<b>82.6</b>	86.5	63
30-Jun-07	22:11	<b>85.6</b>	88	81.5
30-Jun-07	22:16	<b>84.8</b>	87.5	77
30-Jun-07	22:21	<b>84.7</b>	87.5	77
30-Jun-07	22:26	<b>83.6</b>	86	74
30-Jun-07	22:31	<b>83.5</b>	85	76
30-Jun-07	22:36	<b>78.4</b>	84	62
30-Jun-07	22:41	68.4	70.5	64
30-Jun-07	22:46	62.6	65	58.5
30-Jun-07	22:51	60.5	62.5	56.5
30-Jun-07	22:56	62.8	65	58.5
30-Jun-07	23:01	64.3	65	63
30-Jun-07	23:06	63.8	64	62.5
30-Jun-07	23:11	64.1	65	63
30-Jun-07	23:16	63.5	64	62.5
30-Jun-07	23:21	63.1	63.5	62
30-Jun-07	23:26	63	63.5	62
30-Jun-07	23:31	62	63.5	53.5
30-Jun-07	23:36	54.7	56	53.5
30-Jun-07	23:41	61.3	63.5	54.5
30-Jun-07	23:46	55.6	56.5	54
30-Jun-07	23:51	57.8	59.5	55
30-Jun-07	23:56	61.3	61.5	55.5

30-Minute Measurements		
Date	Time	Leq