

**Central Reclamation Phase III**  
**Continuous Noise Monitoring Result - City Hall**

Weather Condition:

Date	Time	5-Minute Measurements		
		Leq	L10	L90
31-Mar-07	0:04	62.6	65.5	59
31-Mar-07	0:09	65	66.5	59.5
31-Mar-07	0:14	59.1	59	58.5
31-Mar-07	0:19	59	59	58.5
31-Mar-07	0:24	59	59	58.5
31-Mar-07	0:29	60.9	60	58.5
31-Mar-07	0:34	59	59	58.5
31-Mar-07	0:39	59	59	58.5
31-Mar-07	0:44	58.9	59	58.5
31-Mar-07	0:49	58.9	59	58.5
31-Mar-07	0:54	59	59	58.5
31-Mar-07	0:59	58.9	59	58.5
31-Mar-07	1:04	58.9	59	58.5
31-Mar-07	1:09	58.9	59	58.5
31-Mar-07	1:14	59.2	59.5	58.5
31-Mar-07	1:19	59.1	59	58.5
31-Mar-07	1:24	58.9	59	58.5
31-Mar-07	1:29	59.4	59.5	58.5
31-Mar-07	1:34	62.9	65.5	58.5
31-Mar-07	1:39	59.5	60	59
31-Mar-07	1:44	59.1	59	58.5
31-Mar-07	1:49	60	60	58.5
31-Mar-07	1:54	59.3	59.5	58.5
31-Mar-07	1:59	58.9	59	58.5
31-Mar-07	2:04	58.8	59	58.5
31-Mar-07	2:09	59	59	58.5
31-Mar-07	2:14	59.2	59	58.5
31-Mar-07	2:19	59.5	60	58.5
31-Mar-07	2:24	58.9	59	58.5
31-Mar-07	2:29	58.9	59	58.5
31-Mar-07	2:34	59.1	59.5	58.5
31-Mar-07	2:39	59.4	59.5	58.5
31-Mar-07	2:44	59	59.5	58.5
31-Mar-07	2:49	58.9	59	58.5
31-Mar-07	2:54	58.9	59	58.5
31-Mar-07	2:59	58.8	59	58.5
31-Mar-07	3:04	59	59	58.5
31-Mar-07	3:09	58.9	59	58.5
31-Mar-07	3:14	58.8	59	58.5
31-Mar-07	3:19	59	59	58.5
31-Mar-07	3:24	59.1	59	58.5
31-Mar-07	3:29	59	59	58.5
31-Mar-07	3:34	58.9	59	58.5
31-Mar-07	3:39	59.1	59.5	58.5
31-Mar-07	3:44	59.1	59	58.5
31-Mar-07	3:49	59.1	59.5	58.5
31-Mar-07	3:54	59	59	58.5
31-Mar-07	3:59	59	59	58.5
31-Mar-07	4:04	59	59	58.5
31-Mar-07	4:09	59.2	59	58.5
31-Mar-07	4:14	59.1	59.5	58.5
31-Mar-07	4:19	58.9	59	58.5
31-Mar-07	4:24	58.9	59	58.5
31-Mar-07	4:29	58.9	59	58.5
31-Mar-07	4:34	59	59	58.5
31-Mar-07	4:39	59	59	58.5
31-Mar-07	4:44	59.1	59	58.5
31-Mar-07	4:49	58.9	59	58.5
31-Mar-07	4:54	59.1	59.5	58.5
31-Mar-07	4:59	58.9	59	58.5
31-Mar-07	5:04	58.9	59	58.5
31-Mar-07	5:09	59.3	60	58.5
31-Mar-07	5:14	59	59	58.5
31-Mar-07	5:19	59.1	59.5	58.5
31-Mar-07	5:24	58.8	59	58.5
31-Mar-07	5:29	58.9	59	58.5
31-Mar-07	5:34	59.1	59.5	58.5
31-Mar-07	5:39	59	59	58.5
31-Mar-07	5:44	59.3	59.5	58.5
31-Mar-07	5:49	59.6	60	59

30-Minute Measurements		
Date	Time	Leq
31-Mar-07	0:04	61.6
31-Mar-07	0:34	59.0
31-Mar-07	1:04	59.1
31-Mar-07	1:34	60.2
31-Mar-07	2:04	59.1
31-Mar-07	2:34	59.0
31-Mar-07	3:04	59.0
31-Mar-07	3:34	59.0
31-Mar-07	4:04	59.0
31-Mar-07	4:34	59.0
31-Mar-07	5:04	59.0
31-Mar-07	5:34	59.5
31-Mar-07	6:04	59.9
31-Mar-07	6:34	60.5
31-Mar-07	7:04	63.5
31-Mar-07	7:34	65.6
31-Mar-07	8:04	66.5
31-Mar-07	8:34	67.6
31-Mar-07	9:04	66.7
31-Mar-07	9:34	68.1
31-Mar-07	10:04	68.2
31-Mar-07	10:34	66.7
31-Mar-07	11:04	66.5
31-Mar-07	11:34	65.3
31-Mar-07	12:04	64.9
31-Mar-07	12:34	64.9
31-Mar-07	13:04	66.9
31-Mar-07	13:34	69.6
31-Mar-07	14:04	66.6
31-Mar-07	14:34	67.3
31-Mar-07	15:04	65.0
31-Mar-07	15:34	66.2
31-Mar-07	16:04	66.6
31-Mar-07	16:34	66.5
31-Mar-07	17:04	67.7
31-Mar-07	17:34	66.2
31-Mar-07	18:04	64.5
31-Mar-07	18:34	64.1
31-Mar-07	19:04	65.3
31-Mar-07	19:34	64.2
31-Mar-07	20:04	62.5
31-Mar-07	20:34	62.9
31-Mar-07	21:04	62.0
31-Mar-07	21:34	60.7
31-Mar-07	22:04	61.8
31-Mar-07	22:34	61.8
31-Mar-07	23:04	60.5
31-Mar-07	23:34	59.8

Date	Time	5-Minute Measurements		
		Leq	L10	L90
31-Mar-07	5:54	60.1	61	59
31-Mar-07	5:59	60	61	59
31-Mar-07	6:04	59.9	61	59
31-Mar-07	6:09	59.9	60.5	59
31-Mar-07	6:14	59.9	60.5	59
31-Mar-07	6:19	59.6	60.5	59
31-Mar-07	6:24	59.8	60.5	59
31-Mar-07	6:29	60.4	61	59.5
31-Mar-07	6:34	60.9	62	59.5
31-Mar-07	6:39	60.4	61.5	59
31-Mar-07	6:44	59.5	59.5	59
31-Mar-07	6:49	59.8	60.5	59
31-Mar-07	6:54	60.6	61.5	59.5
31-Mar-07	6:59	61.3	61.5	59.5
31-Mar-07	7:04	62.6	64	60
31-Mar-07	7:09	63.6	64.5	61.5
31-Mar-07	7:14	63.3	64.5	60.5
31-Mar-07	7:19	63.7	65	62
31-Mar-07	7:24	64.6	66	62.5
31-Mar-07	7:29	63.2	64.5	61.5
31-Mar-07	7:34	63.3	65	61.5
31-Mar-07	7:39	65	65.5	63.5
31-Mar-07	7:44	64.9	66.5	62.5
31-Mar-07	7:49	66.5	67.5	64
31-Mar-07	7:54	64.7	66.5	62
31-Mar-07	7:59	67.9	70.5	64.5
31-Mar-07	8:04	66	68.5	60.5
31-Mar-07	8:09	66.6	69	64
31-Mar-07	8:14	67.7	69	64
31-Mar-07	8:19	66	67	64.5
31-Mar-07	8:24	66.8	68	65
31-Mar-07	8:29	65.9	67	64
31-Mar-07	8:34	67.2	69	64
31-Mar-07	8:39	66.1	67.5	65
31-Mar-07	8:44	66.7	68	64.5
31-Mar-07	8:49	68.7	69.5	67
31-Mar-07	8:54	68.2	69	66.5
31-Mar-07	8:59	68.1	70.5	65
31-Mar-07	9:04	67.5	68.5	65.5
31-Mar-07	9:09	66.8	67.5	65
31-Mar-07	9:14	65.8	66.5	64.5
31-Mar-07	9:19	66.4	67.5	64
31-Mar-07	9:24	67.8	70	64.5
31-Mar-07	9:29	65.4	66.5	64
31-Mar-07	9:34	65.4	66.5	63.5
31-Mar-07	9:39	66.3	68	63.5
31-Mar-07	9:44	66.7	69	63
31-Mar-07	9:49	70.7	71.5	67
31-Mar-07	9:54	68.7	70.5	66
31-Mar-07	9:59	68.3	69	65
31-Mar-07	10:04	66.2	68	62
31-Mar-07	10:09	66.5	68.5	63
31-Mar-07	10:14	65.5	67.5	63
31-Mar-07	10:19	66.6	68	64.5
31-Mar-07	10:24	69.6	70.5	66
31-Mar-07	10:29	71.5	69.5	65
31-Mar-07	10:34	67.4	68.5	66
31-Mar-07	10:39	67.4	68	66
31-Mar-07	10:44	66.8	68	65
31-Mar-07	10:49	65.7	66.5	64
31-Mar-07	10:54	66.5	67	65
31-Mar-07	10:59	66.4	67.5	64.5
31-Mar-07	11:04	65.4	67	63.5
31-Mar-07	11:09	65.8	67	64
31-Mar-07	11:14	66.8	67.5	65
31-Mar-07	11:19	67.1	68.5	65
31-Mar-07	11:24	67.5	69.5	65.5
31-Mar-07	11:29	66.1	67	64
31-Mar-07	11:34	65	66	63
31-Mar-07	11:39	64.6	65.5	62.5
31-Mar-07	11:44	64.8	66	62
31-Mar-07	11:49	65.8	67.5	63.5
31-Mar-07	11:54	65.4	67	62.5
31-Mar-07	11:59	66	67	64
31-Mar-07	12:04	66.3	69	63

30-Minute Measurements		
Date	Time	Leq

Date	Time	5-Minute Measurements		
		Leq	L10	L90
31-Mar-07	12:09	64.8	66	61.5
31-Mar-07	12:14	63.7	65.5	61
31-Mar-07	12:19	63	64	61
31-Mar-07	12:24	66.2	67	63.5
31-Mar-07	12:29	64.1	66	61
31-Mar-07	12:34	64.4	66.5	62
31-Mar-07	12:39	65	66	63
31-Mar-07	12:44	66	68	61.5
31-Mar-07	12:49	63.8	65.5	60
31-Mar-07	12:54	66.3	67.5	64
31-Mar-07	12:59	63.2	65	60.5
31-Mar-07	13:04	63.7	64	60.5
31-Mar-07	13:09	64.8	66	63
31-Mar-07	13:14	65.1	67.5	61.5
31-Mar-07	13:19	66.1	68	62
31-Mar-07	13:24	69.4	70.5	66
31-Mar-07	13:29	68.9	70.5	66
31-Mar-07	13:34	70.7	72.5	68
31-Mar-07	13:39	69.7	72	67
31-Mar-07	13:44	71.1	73.5	67.5
31-Mar-07	13:49	68.8	72.5	64
31-Mar-07	13:54	68.8	71	66
31-Mar-07	13:59	67.1	69	64
31-Mar-07	14:04	67.3	69	64.5
31-Mar-07	14:09	65.6	67.5	62
31-Mar-07	14:14	63	65.5	60
31-Mar-07	14:19	64.2	66	61
31-Mar-07	14:24	68.5	70	65
31-Mar-07	14:29	68.1	70	64
31-Mar-07	14:34	67.5	69.5	64
31-Mar-07	14:39	67.3	69.5	63.5
31-Mar-07	14:44	66.5	68.5	63
31-Mar-07	14:49	65.7	68	63
31-Mar-07	14:54	68.2	70	65.5
31-Mar-07	14:59	68.1	70.5	63.5
31-Mar-07	15:04	65.8	67.5	61
31-Mar-07	15:09	66.2	67	64
31-Mar-07	15:14	65	66	62.5
31-Mar-07	15:19	63.6	66	59
31-Mar-07	15:24	63.3	65	59
31-Mar-07	15:29	65.3	67	62
31-Mar-07	15:34	65.7	67.5	61
31-Mar-07	15:39	66.1	67.5	62.5
31-Mar-07	15:44	68.2	69	64.5
31-Mar-07	15:49	65.7	67	64
31-Mar-07	15:54	65.7	67	63.5
31-Mar-07	15:59	65.2	66.5	62
31-Mar-07	16:04	66.6	67	63
31-Mar-07	16:09	66.6	68	63.5
31-Mar-07	16:14	66.9	68	65
31-Mar-07	16:19	64.8	68	59.5
31-Mar-07	16:24	67.6	70	62.5
31-Mar-07	16:29	66.5	68	63
31-Mar-07	16:34	67.2	70	63.5
31-Mar-07	16:39	65.8	67	63.5
31-Mar-07	16:44	66.2	68	62.5
31-Mar-07	16:49	65.9	68.5	62.5
31-Mar-07	16:54	67.9	69.5	64.5
31-Mar-07	16:59	65.6	67	63
31-Mar-07	17:04	65	66.5	63
31-Mar-07	17:09	68.7	68	63
31-Mar-07	17:14	68.1	70.5	63.5
31-Mar-07	17:19	67.6	67	63.5
31-Mar-07	17:24	67.6	69	65.5
31-Mar-07	17:29	68.1	69.5	65.5
31-Mar-07	17:34	66.9	69.5	64.5
31-Mar-07	17:39	66.8	68	64.5
31-Mar-07	17:44	66	67	64
31-Mar-07	17:49	65.5	66.5	62.5
31-Mar-07	17:54	65.7	67.5	62.5
31-Mar-07	17:59	66	67.5	64
31-Mar-07	18:04	65.2	67	62.5
31-Mar-07	18:09	64	65.5	62
31-Mar-07	18:14	63.8	65	62
31-Mar-07	18:19	63.8	65	62.5

30-Minute Measurements		
Date	Time	Leq

Date	Time	5-Minute Measurements		
		Leq	L10	L90
31-Mar-07	18:24	64.7	66	62.5
31-Mar-07	18:29	65.1	66	63
31-Mar-07	18:34	64.2	65	62.5
31-Mar-07	18:39	64.8	66.5	62.5
31-Mar-07	18:44	65.3	67	63
31-Mar-07	18:49	63	64	61.5
31-Mar-07	18:54	63.7	65	61.5
31-Mar-07	18:59	63.4	64.5	61.5
31-Mar-07	19:04	64.1	65.5	62.5
31-Mar-07	19:09	64.8	65.5	63
31-Mar-07	19:14	64.3	66	61.5
31-Mar-07	19:19	64.9	66.5	63
31-Mar-07	19:24	66.6	67.5	64.5
31-Mar-07	19:29	66.2	68	63
31-Mar-07	19:34	63.7	65	61
31-Mar-07	19:39	64.2	65.5	62
31-Mar-07	19:44	64.7	66	63
31-Mar-07	19:49	64.8	66.5	62
31-Mar-07	19:54	64.6	65.5	62.5
31-Mar-07	19:59	63.1	65	61
31-Mar-07	20:04	61.3	62	59.5
31-Mar-07	20:09	62.9	65	60
31-Mar-07	20:14	61.7	63.5	59.5
31-Mar-07	20:19	61.5	63	59.5
31-Mar-07	20:24	63	64.5	60.5
31-Mar-07	20:29	63.9	65.5	60.5
31-Mar-07	20:34	60.9	61.5	59.5
31-Mar-07	20:39	66.3	68	60.5
31-Mar-07	20:44	61.7	62.5	60
31-Mar-07	20:49	60.5	61	59.5
31-Mar-07	20:54	62.9	64	59.5
31-Mar-07	20:59	62.1	64	59.5
31-Mar-07	21:04	60.4	61	59.5
31-Mar-07	21:09	62.9	64	60
31-Mar-07	21:14	63.4	65.5	61.5
31-Mar-07	21:19	61.8	63	60
31-Mar-07	21:24	61.7	63	60
31-Mar-07	21:29	61.4	63	59.5
31-Mar-07	21:34	61	62	59.5
31-Mar-07	21:39	60	60.5	59.5
31-Mar-07	21:44	60.5	61	59.5
31-Mar-07	21:49	60.7	61.5	59.5
31-Mar-07	21:54	60.1	60.5	59
31-Mar-07	21:59	61.8	63	59.5
31-Mar-07	22:04	63.1	65	60
31-Mar-07	22:09	62.6	64	60
31-Mar-07	22:14	62.6	64.5	59.5
31-Mar-07	22:19	60.4	61	59
31-Mar-07	22:24	60.5	60.5	59.5
31-Mar-07	22:29	60.9	61.5	59.5
31-Mar-07	22:34	60.3	61	59.5
31-Mar-07	22:39	62.2	64	59.5
31-Mar-07	22:44	63.2	65	60.5
31-Mar-07	22:49	60.9	61.5	59.5
31-Mar-07	22:54	62.7	64.5	60.5
31-Mar-07	22:59	60.3	60.5	59.5
31-Mar-07	23:04	61	62	59.5
31-Mar-07	23:09	61	62	59.5
31-Mar-07	23:14	61.2	62	59
31-Mar-07	23:19	59.9	60.5	59
31-Mar-07	23:24	59.9	60	59
31-Mar-07	23:29	59.5	59.5	59
31-Mar-07	23:34	59.3	59.5	59
31-Mar-07	23:39	59.3	59.5	59
31-Mar-07	23:44	60.6	62	59
31-Mar-07	23:49	60.3	60	59
31-Mar-07	23:54	60.1	60	59
31-Mar-07	23:59	59.1	59	58.5

30-Minute Measurements		
Date	Time	Leq