

**Central Reclamation Phase III
TSP Monitoring Result**

| STATION | Date | Weather Condition | 24-hour TSP conc., $\mu\text{g}/\text{m}^3$ | Date | 1-hour TSP conc., $\mu\text{g}/\text{m}^3$ | Time | |
|-----------|-----------|-------------------|---|----------|--|-------|-------|
| | | | | | | | |
| PLA | 01-Feb-06 | Fine | 76 | 3-Feb-06 | 136 | 8:46 | 9:46 |
| | | | | | 141 | 9:46 | 10:46 |
| | | | | | 135 | 10:46 | 11:46 |
| City Hall | - | - | - | | - | - | - |
| | | | | | - | - | - |
| | | | | | - | - | - |

| STATION | Date | Weather Condition | 24-hour TSP conc., $\mu\text{g}/\text{m}^3$ | Date | 1-hour TSP conc., $\mu\text{g}/\text{m}^3$ | Time | |
|-----------|-----------|-------------------|---|-----------|--|-------|-------|
| | | | | | | | |
| PLA | 07-Feb-06 | Fine | 84 | 09-Feb-06 | 135 | 9:11 | 10:11 |
| | | | | | 116 | 10:11 | 11:11 |
| | | | | | 111 | 11:11 | 12:11 |
| City Hall | - | - | - | | - | - | - |
| | | | | | - | - | - |
| | | | | | - | - | - |

| STATION | Date | Weather Condition | 24-hour TSP conc., $\mu\text{g}/\text{m}^3$ | Date | 1-hour TSP conc., $\mu\text{g}/\text{m}^3$ | Time | |
|-----------|-----------|-------------------|---|-----------|--|-------|-------|
| | | | | | | | |
| PLA | 15-Feb-06 | Fine | 91 | 17-Feb-06 | 142 | 09:31 | 10:31 |
| | | | | | 143 | 10:31 | 11:31 |
| | | | | | 122 | 11:31 | 12:31 |
| City Hall | - | - | - | | - | - | - |
| | | | | | - | - | - |
| | | | | | - | - | - |

| STATION | Date | Weather Condition | 24-hour TSP conc., $\mu\text{g}/\text{m}^3$ | Date | 1-hour TSP conc., $\mu\text{g}/\text{m}^3$ | Time | |
|-----------|------|-------------------|---|-----------|--|-------|-------|
| | | | | | | | |
| PLA | | | | 24-Feb-06 | 271 | 14:01 | 15:01 |
| | | | | | 271 | 15:01 | 16:01 |
| | | | | | 251 | 16:01 | 16:30 |
| City Hall | - | - | - | | - | - | - |
| | | | | | - | - | - |
| | | | | | - | - | - |

General Remarks:

Monitoring was not conducted at the City Hall monitoring station because exterior renovation works were undertaken by City Hall at the elevated walkway area.

24hr Sampling results for last week of February incomplete due to HVS equipment malfunction