

**Central Reclamation Phase III
Continuous Noise Monitoring Result - City Hall**

Weather Condition:

Date	Time	5-Minute Measurements		
		Leq	L10	L90
31-Jan-07	0:03	60.6	61	59.5
31-Jan-07	0:08	60	60	59.5
31-Jan-07	0:13	60	60	59.5
31-Jan-07	0:18	60.1	60	59.5
31-Jan-07	0:23	60.4	60.5	59.5
31-Jan-07	0:28	60	60	59.5
31-Jan-07	0:33	59.9	60	59.5
31-Jan-07	0:38	60.7	61.5	59.5
31-Jan-07	0:43	60.2	60.5	59.5
31-Jan-07	0:48	59.9	60	59.5
31-Jan-07	0:53	60	60	59.5
31-Jan-07	0:58	60.3	60.5	59.5
31-Jan-07	1:03	59.9	60	59.5
31-Jan-07	1:08	60.1	60.5	59.5
31-Jan-07	1:13	59.8	60	59.5
31-Jan-07	1:18	59.9	60	59.5
31-Jan-07	1:23	59.8	60	59.5
31-Jan-07	1:28	61.2	62	59.5
31-Jan-07	1:33	62.2	64.5	59.5
31-Jan-07	1:38	60.2	60	59.5
31-Jan-07	1:43	59.9	60	59.5
31-Jan-07	1:48	60.1	60.5	59.5
31-Jan-07	1:53	59.9	60	59.5
31-Jan-07	1:58	60.1	60	59.5
31-Jan-07	2:03	60.3	61	59.5
31-Jan-07	2:08	59.9	60	59.5
31-Jan-07	2:13	60	60.5	59.5
31-Jan-07	2:18	59.9	60	59.5
31-Jan-07	2:23	60.4	61.5	59.5
31-Jan-07	2:28	59.9	60	59.5
31-Jan-07	2:33	60	60.5	59.5
31-Jan-07	2:38	59.8	60	59.5
31-Jan-07	2:43	60.1	60.5	59.5
31-Jan-07	2:48	60.1	60.5	59.5
31-Jan-07	2:53	60.2	60.5	59.5
31-Jan-07	2:58	60.1	60	59.5
31-Jan-07	3:03	60.1	60.5	59.5
31-Jan-07	3:08	60.2	60.5	59.5
31-Jan-07	3:13	60.2	60.5	59.5
31-Jan-07	3:18	60.1	60	59.5
31-Jan-07	3:23	60.3	60.5	60
31-Jan-07	3:28	60.6	61	60
31-Jan-07	3:33	61.1	61.5	60
31-Jan-07	3:38	61	61.5	60
31-Jan-07	3:43	61.4	62	60.5
31-Jan-07	3:48	60.8	61	60
31-Jan-07	3:53	60.3	60.5	60
31-Jan-07	3:58	60.1	60.5	59.5
31-Jan-07	4:03	60.2	60.5	59.5
31-Jan-07	4:08	60	60	59.5
31-Jan-07	4:13	59.9	60	59.5
31-Jan-07	4:18	60.1	60	59.5
31-Jan-07	4:23	60	60	59.5
31-Jan-07	4:28	60	60	59.5
31-Jan-07	4:33	59.9	60	59.5
31-Jan-07	4:38	59.9	60	59.5
31-Jan-07	4:43	60.2	60.5	60
31-Jan-07	4:48	60.1	60	59.5
31-Jan-07	4:53	60.6	60.5	59.5
31-Jan-07	4:58	60.5	60.5	60
31-Jan-07	5:03	60.2	60.5	59.5
31-Jan-07	5:08	60.2	60.5	59.5
31-Jan-07	5:13	60.3	60.5	60
31-Jan-07	5:18	60.4	60.5	60
31-Jan-07	5:23	60.5	61	60
31-Jan-07	5:28	60.4	61	60
31-Jan-07	5:33	60.8	61.5	60
31-Jan-07	5:38	60.3	60.5	60
31-Jan-07	5:43	60.5	61	60
31-Jan-07	5:48	60.7	61	60

30-Minute Measurements		
Date	Time	Leq
31-Jan-07	0:18	60.2
31-Jan-07	0:48	60.0
31-Jan-07	1:18	60.6
31-Jan-07	1:48	60.1
31-Jan-07	2:18	60.0
31-Jan-07	2:48	60.2
31-Jan-07	3:18	60.8
31-Jan-07	3:48	60.2
31-Jan-07	4:18	60.0
31-Jan-07	4:48	60.3
31-Jan-07	5:18	60.5
31-Jan-07	5:48	61.2
31-Jan-07	6:18	61.3
31-Jan-07	6:48	61.4
31-Jan-07	7:18	66.1
31-Jan-07	7:48	62.8
31-Jan-07	8:18	70.2
31-Jan-07	8:48	69.1
31-Jan-07	9:18	71.3
31-Jan-07	9:48	68.2
31-Jan-07	10:18	68.8
31-Jan-07	10:48	67.9
31-Jan-07	11:18	67.0
31-Jan-07	11:48	65.4
31-Jan-07	12:18	63.9
31-Jan-07	12:48	68.2
31-Jan-07	13:18	67.7
31-Jan-07	13:48	66.1
31-Jan-07	14:18	66.0
31-Jan-07	14:48	64.6
31-Jan-07	15:18	66.0
31-Jan-07	15:48	65.0
31-Jan-07	16:18	67.9
31-Jan-07	16:48	66.9
31-Jan-07	17:18	68.0
31-Jan-07	17:49	64.4
31-Jan-07	18:19	64.8
31-Jan-07	18:49	64.4
31-Jan-07	19:19	65.0
31-Jan-07	19:49	63.4
31-Jan-07	20:19	62.1
31-Jan-07	20:49	61.7
31-Jan-07	21:19	61.6
31-Jan-07	21:49	61.4
31-Jan-07	22:19	61.0
31-Jan-07	22:49	61.2
31-Jan-07	23:19	63.5
31-Jan-07	23:49	69.2

Date	Time	5-Minute Measurements		
		Leq	L10	L90
31-Jan-07	5:53	61.2	61.5	60.5
31-Jan-07	5:58	61.1	61.5	60.5
31-Jan-07	6:03	61.4	62	60.5
31-Jan-07	6:08	61.3	62	60.5
31-Jan-07	6:13	61.5	62	61
31-Jan-07	6:18	61.2	61.5	60.5
31-Jan-07	6:23	61.5	62	60.5
31-Jan-07	6:28	61	61.5	60
31-Jan-07	6:33	60.8	61.5	60
31-Jan-07	6:38	61.8	63	60.5
31-Jan-07	6:43	61.3	62	60
31-Jan-07	6:48	61.3	62	60
31-Jan-07	6:53	60.8	61	60
31-Jan-07	6:58	61	61.5	60
31-Jan-07	7:03	61.9	63.5	60.5
31-Jan-07	7:08	61.3	62	60.5
31-Jan-07	7:13	62.1	63.5	59.5
31-Jan-07	7:18	61.5	62.5	60
31-Jan-07	7:23	65	67.5	61.5
31-Jan-07	7:28	63.3	66	58.5
31-Jan-07	7:33	70.7	65.5	60.5
31-Jan-07	7:38	66.1	64	59.5
31-Jan-07	7:43	62.2	64.5	57.5
31-Jan-07	7:48	63.6	64.5	58.5
31-Jan-07	7:53	61	63.5	56.5
31-Jan-07	7:58	60.2	61	59
31-Jan-07	8:03	60.5	63	56.5
31-Jan-07	8:08	63	64.5	56.5
31-Jan-07	8:13	65.8	66.5	61.5
31-Jan-07	8:18	70	73	61.5
31-Jan-07	8:23	70.5	71.5	62
31-Jan-07	8:28	71.6	73	64
31-Jan-07	8:33	64	66.5	58.5
31-Jan-07	8:38	70.5	72	61.5
31-Jan-07	8:43	71.3	74.5	64.5
31-Jan-07	8:48	71.8	74.5	64.5
31-Jan-07	8:53	66.5	69	63
31-Jan-07	8:58	67.4	70	63.5
31-Jan-07	9:03	68.8	70.5	65
31-Jan-07	9:08	67.4	70	63
31-Jan-07	9:13	70.4	75	63
31-Jan-07	9:18	73.9	77	65
31-Jan-07	9:23	73	76	64
31-Jan-07	9:28	65.1	67	60
31-Jan-07	9:33	67.3	69.5	59
31-Jan-07	9:38	71.2	74	67
31-Jan-07	9:43	71.4	74.5	67.5
31-Jan-07	9:48	71.2	75	63
31-Jan-07	9:53	65.5	69	60
31-Jan-07	9:58	69.1	70	60
31-Jan-07	10:03	61.7	63	57
31-Jan-07	10:08	67.4	69.5	60
31-Jan-07	10:13	69	70.5	67.5
31-Jan-07	10:18	69.2	70	68
31-Jan-07	10:23	69	71.5	65
31-Jan-07	10:28	67.8	69.5	64
31-Jan-07	10:33	69.8	72	66
31-Jan-07	10:38	69.5	71.5	67
31-Jan-07	10:43	67	68	65.5
31-Jan-07	10:48	65.3	68	59
31-Jan-07	10:53	64.4	68	58.5
31-Jan-07	10:58	69.3	70.5	66.5
31-Jan-07	11:03	70.4	71	67
31-Jan-07	11:08	69.5	72.5	63
31-Jan-07	11:13	63.5	64	58.5
31-Jan-07	11:18	65.9	68.5	61.5
31-Jan-07	11:23	63.5	65.5	59.5
31-Jan-07	11:28	63	65	59.5
31-Jan-07	11:33	64.3	66.5	61.5
31-Jan-07	11:38	63.6	65.5	60
31-Jan-07	11:43	72.3	75.5	62.5
31-Jan-07	11:48	69.8	72.5	63
31-Jan-07	11:53	64.1	66	61.5
31-Jan-07	11:58	64.3	65.5	62
31-Jan-07	12:03	64.1	65	61.5

30-Minute Measurements		
Date	Time	Leq

Date	Time	5-Minute Measurements		
		Leq	L10	L90
31-Jan-07	12:08	62	62.5	60
31-Jan-07	12:13	62.9	64	61
31-Jan-07	12:18	62.7	63.5	61.5
31-Jan-07	12:23	64.2	65.5	62
31-Jan-07	12:28	65	66.5	62.5
31-Jan-07	12:33	64.9	66.5	62.5
31-Jan-07	12:38	64	66.5	60.5
31-Jan-07	12:43	62	63.5	60.5
31-Jan-07	12:48	61.9	64	60
31-Jan-07	12:53	64	66	60.5
31-Jan-07	12:58	68.4	68.5	66
31-Jan-07	13:03	71.4	68	66
31-Jan-07	13:08	69.7	69	65.5
31-Jan-07	13:13	67.5	68.5	64
31-Jan-07	13:18	68.3	71.5	63.5
31-Jan-07	13:23	69.1	72	64
31-Jan-07	13:28	70.1	71	64.5
31-Jan-07	13:33	66	68.5	63.5
31-Jan-07	13:38	65	66	63.5
31-Jan-07	13:43	65.4	66.5	63.5
31-Jan-07	13:48	64.7	66	63
31-Jan-07	13:53	65.7	67.5	63.5
31-Jan-07	13:58	65.8	67	64
31-Jan-07	14:03	67.6	68.5	65
31-Jan-07	14:08	66.1	67	65
31-Jan-07	14:13	65.9	66	63
31-Jan-07	14:18	66	67	63.5
31-Jan-07	14:23	66.4	66	62.5
31-Jan-07	14:28	64.8	67	62
31-Jan-07	14:33	64.5	67	62
31-Jan-07	14:38	66	69.5	62
31-Jan-07	14:43	67.4	70.5	62
31-Jan-07	14:48	67.6	70.5	62.5
31-Jan-07	14:53	62.8	64	61
31-Jan-07	14:58	63.3	64.5	61
31-Jan-07	15:03	63.9	66	61
31-Jan-07	15:08	63.6	64.5	61.5
31-Jan-07	15:13	64.4	66	62
31-Jan-07	15:18	64.6	67	61.5
31-Jan-07	15:23	63.4	65	61
31-Jan-07	15:28	67.5	72	61.5
31-Jan-07	15:33	69	72.5	62.5
31-Jan-07	15:38	63.6	65	61.5
31-Jan-07	15:43	64.7	66	61
31-Jan-07	15:48	63.1	65	61
31-Jan-07	15:53	63.5	65	61.5
31-Jan-07	15:58	65.5	67.5	62.5
31-Jan-07	16:03	64.4	66	61.5
31-Jan-07	16:08	66.7	67.5	61.5
31-Jan-07	16:13	65.9	68	62.5
31-Jan-07	16:18	63.1	64.5	61.5
31-Jan-07	16:23	64.6	66.5	61.5
31-Jan-07	16:28	72.8	76	66.5
31-Jan-07	16:33	67.4	69.5	62
31-Jan-07	16:38	65	66.5	63
31-Jan-07	16:43	66.5	69	63
31-Jan-07	16:48	66	68	63.5
31-Jan-07	16:53	66.4	68	63.5
31-Jan-07	16:58	67.3	68.5	64
31-Jan-07	17:03	67.1	68.5	64.5
31-Jan-07	17:08	66.9	69	63.5
31-Jan-07	17:13	67.3	69	64
31-Jan-07	17:18	68.3	70.5	65
31-Jan-07	17:23	68.9	71	66
31-Jan-07	17:28	67.5	69.5	64.5
31-Jan-07	17:33	68.2	70.5	64
31-Jan-07	17:38	68.1	70	65.5
31-Jan-07	17:43	66.9	68.5	65
31-Jan-07	17:49	63.9	65	62
31-Jan-07	17:54	64.2	66	62.5
31-Jan-07	17:59	65.2	66.5	62.5
31-Jan-07	18:04	64.5	67	61.5
31-Jan-07	18:09	64.1	66	61.5
31-Jan-07	18:14	64.4	66	62
31-Jan-07	18:19	65	67	62.5

30-Minute Measurements		
Date	Time	Leq

Date	Time	5-Minute Measurements		
		Leq	L10	L90
31-Jan-07	18:24	64.8	66.5	62.5
31-Jan-07	18:29	64.1	66.5	61.5
31-Jan-07	18:34	63.7	65.5	61.5
31-Jan-07	18:39	66.5	67.5	61.5
31-Jan-07	18:44	64.3	66	61.5
31-Jan-07	18:49	63.5	65	61.5
31-Jan-07	18:54	63.8	65	62.5
31-Jan-07	18:59	65	66.5	63
31-Jan-07	19:04	64.2	66	61.5
31-Jan-07	19:09	64.8	67	61.5
31-Jan-07	19:14	64.7	67	62
31-Jan-07	19:19	66.2	69	62
31-Jan-07	19:24	66.9	68.5	65
31-Jan-07	19:29	65.9	69	61.5
31-Jan-07	19:34	62.6	64	60.5
31-Jan-07	19:39	62.5	63.5	61
31-Jan-07	19:44	63.7	65.5	61.5
31-Jan-07	19:49	63.3	65	60.5
31-Jan-07	19:54	64.1	65.5	61.5
31-Jan-07	19:59	64.5	66	61
31-Jan-07	20:04	62	63.5	60.5
31-Jan-07	20:09	63.5	66	61
31-Jan-07	20:14	62.3	64	60.5
31-Jan-07	20:19	61.4	62	60
31-Jan-07	20:24	64.1	65.5	60.5
31-Jan-07	20:29	62.4	64	60.5
31-Jan-07	20:34	60.9	61	60
31-Jan-07	20:39	61.1	62	60
31-Jan-07	20:44	61.7	63	60.5
31-Jan-07	20:49	61.3	61.5	60.5
31-Jan-07	20:54	61.3	62.5	60
31-Jan-07	20:59	60.9	61	60
31-Jan-07	21:04	61.1	61.5	60
31-Jan-07	21:09	64.1	67	60.5
31-Jan-07	21:14	60.5	61	59.5
31-Jan-07	21:19	62	64.5	60
31-Jan-07	21:24	60.6	61.5	60
31-Jan-07	21:29	61	62	60
31-Jan-07	21:34	60.7	61	60
31-Jan-07	21:39	63	65.5	60.5
31-Jan-07	21:44	61.5	62.5	60.5
31-Jan-07	21:49	61.4	62	60
31-Jan-07	21:54	60.5	61	60
31-Jan-07	21:59	61.5	62.5	60
31-Jan-07	22:04	62.5	63.5	60
31-Jan-07	22:09	61.2	62	60
31-Jan-07	22:14	60.9	61.5	59.5
31-Jan-07	22:19	62	64	60
31-Jan-07	22:24	60.6	61	60
31-Jan-07	22:29	60.5	61	60
31-Jan-07	22:34	60.5	61	60
31-Jan-07	22:39	60.9	61.5	60
31-Jan-07	22:44	61.1	62	60
31-Jan-07	22:49	61.6	62.5	60
31-Jan-07	22:54	61.1	62	59.5
31-Jan-07	22:59	62.1	63	60.5
31-Jan-07	23:04	60.7	61.5	60
31-Jan-07	23:09	60.7	61.5	60
31-Jan-07	23:14	60.8	61.5	59.5
31-Jan-07	23:19	63.7	65.5	61.5
31-Jan-07	23:24	63.7	65.5	61.5
31-Jan-07	23:29	66.1	68.5	61.5
31-Jan-07	23:34	63.5	65	61
31-Jan-07	23:39	60.7	61	60
31-Jan-07	23:44	60.6	60.5	60
31-Jan-07	23:49	72.1	69.5	64
31-Jan-07	23:54	68.2	68.5	67.5
31-Jan-07	23:59	68.3	69	67.5

30-Minute Measurements		
Date	Time	Leq