

**Central Reclamation Phase III**  
**Continuous Noise Monitoring Result - City Hall**

Weather Condition:

Date	Time	5-Minute Measurements		
		Leq	L10	L90
31-May-07	00:04	57.6	59	55.5
31-May-07	00:09	57.7	59	55.5
31-May-07	00:14	56.6	56.5	55.5
31-May-07	00:19	57.7	58	55.5
31-May-07	00:24	57.8	59	55.5
31-May-07	00:29	56.4	57.5	52.5
31-May-07	00:34	56	57.5	52.5
31-May-07	00:39	57.8	62	52
31-May-07	00:44	54.6	55	52
31-May-07	00:49	54	55	51.5
31-May-07	00:54	53.3	54.5	51.5
31-May-07	00:59	52.6	53.5	51.5
31-May-07	01:04	52.4	53.5	51
31-May-07	01:09	52.3	53	51
31-May-07	01:14	52.5	53	51.5
31-May-07	01:19	52.8	53.5	52
31-May-07	01:24	52.6	53.5	51.5
31-May-07	01:29	51.9	52.5	51
31-May-07	01:34	51.9	52.5	51
31-May-07	01:39	51.7	52	51
31-May-07	01:44	51.7	52	51
31-May-07	01:49	51.6	52	51
31-May-07	01:54	51.7	52	51
31-May-07	01:59	51.7	52	51
31-May-07	02:04	52.1	53	51
31-May-07	02:09	53.1	55	51
31-May-07	02:14	52.1	53	51
31-May-07	02:19	51.7	52.5	51
31-May-07	02:24	51.7	52	51
31-May-07	02:29	51.9	52.5	51
31-May-07	02:34	51.8	52.5	51
31-May-07	02:39	51.5	52	50.5
31-May-07	02:44	51	51.5	50.5
31-May-07	02:49	51.4	52	50.5
31-May-07	02:54	52.1	53	51
31-May-07	02:59	51.7	52	51
31-May-07	03:04	52.1	52.5	50.5
31-May-07	03:09	50.9	51.5	50
31-May-07	03:14	50.8	51	50
31-May-07	03:19	50.9	51.5	50
31-May-07	03:24	50.8	51.5	50
31-May-07	03:29	50.7	51.5	50
31-May-07	03:34	50.7	51	50
31-May-07	03:39	51.4	52	50.5
31-May-07	03:44	50.7	51	50
31-May-07	03:49	50.8	51	50
31-May-07	03:54	51.1	51.5	50
31-May-07	03:59	50.8	51.5	50
31-May-07	04:04	51.6	52.5	50.5
31-May-07	04:09	51.3	52	50.5
31-May-07	04:14	51.6	53.5	50
31-May-07	04:19	51.3	52	50
31-May-07	04:24	51.5	52	50.5
31-May-07	04:29	51.1	51.5	50.5
31-May-07	04:34	50.9	51.5	50
31-May-07	04:39	51.4	52	50
31-May-07	04:44	51.8	52	51
31-May-07	04:49	52	53.5	50.5
31-May-07	04:54	51.3	52	50.5
31-May-07	04:59	51.6	52	51
31-May-07	05:04	51.6	52	51
31-May-07	05:09	51.9	52.5	51
31-May-07	05:14	52.1	52.5	51
31-May-07	05:19	53.4	54.5	52
31-May-07	05:24	53.7	54.5	52.5
31-May-07	05:29	52.6	54	51
31-May-07	05:34	51.5	52	50.5
31-May-07	05:39	51.6	52.5	50.5
31-May-07	05:44	52.5	53.5	51
31-May-07	05:49	52.4	53.5	51

30-Minute Measurements		
Date	Time	Leq
31-May-07	00:14	57.1
31-May-07	00:44	53.3
31-May-07	01:14	52.3
31-May-07	01:44	52.0
31-May-07	02:14	51.8
31-May-07	02:44	51.6
31-May-07	03:14	50.9
31-May-07	03:44	51.1
31-May-07	04:14	51.3
31-May-07	04:44	51.7
31-May-07	05:14	52.6
31-May-07	05:44	53.1
31-May-07	06:14	57.6
31-May-07	06:44	60.1
31-May-07	07:14	63.0
31-May-07	07:44	64.0
31-May-07	08:14	65.6
31-May-07	08:44	65.2
31-May-07	09:14	65.2
31-May-07	09:44	64.1
31-May-07	10:14	64.9
31-May-07	10:44	65.4
31-May-07	11:14	68.8
31-May-07	11:44	65.3
31-May-07	12:14	62.0
31-May-07	12:44	62.8
31-May-07	13:14	66.0
31-May-07	13:44	69.0
31-May-07	14:14	70.4
31-May-07	14:44	68.4
31-May-07	15:14	67.3
31-May-07	15:44	67.6
31-May-07	16:14	63.7
31-May-07	16:44	70.0
31-May-07	17:14	69.2
31-May-07	17:44	63.6
31-May-07	18:14	63.2
31-May-07	18:44	62.0
31-May-07	19:14	62.2
31-May-07	19:44	62.1
31-May-07	20:14	59.9
31-May-07	20:44	59.2
31-May-07	21:14	58.3
31-May-07	21:44	57.0
31-May-07	22:14	54.8
31-May-07	22:44	54.8
31-May-07	23:14	61.1
31-May-07	23:44	54.4

Date	Time	5-Minute Measurements		
		Leq	L10	L90
31-May-07	05:54	52	53	51
31-May-07	05:59	54.6	57	52
31-May-07	06:04	52.9	53.5	52
31-May-07	06:09	53.6	54.5	52.5
31-May-07	06:14	58.3	60	55.5
31-May-07	06:19	56	56.5	55
31-May-07	06:24	55.7	56.5	54.5
31-May-07	06:29	56.9	60	54
31-May-07	06:34	59.9	62.5	56.5
31-May-07	06:39	57.2	60	54.5
31-May-07	06:44	56.6	58	54.5
31-May-07	06:49	55.9	56.5	55
31-May-07	06:54	56.4	57.5	55
31-May-07	06:59	58.5	61	55.5
31-May-07	07:04	61.6	63.5	59
31-May-07	07:09	64.4	65.5	63
31-May-07	07:14	61.3	63.5	58
31-May-07	07:19	62.4	65	59
31-May-07	07:24	63.2	65.5	60.5
31-May-07	07:29	62.4	63.5	60.5
31-May-07	07:34	63.3	65	60
31-May-07	07:39	64.7	66	62.5
31-May-07	07:44	64.3	66.5	61.5
31-May-07	07:49	62.9	64	61
31-May-07	07:54	65.9	67	62
31-May-07	07:59	64	66	62
31-May-07	08:04	62.7	64.5	60
31-May-07	08:09	63	65.5	59.5
31-May-07	08:14	65.3	66.5	63
31-May-07	08:19	66	67.5	63.5
31-May-07	08:24	65.5	67	63
31-May-07	08:29	65	66.5	62.5
31-May-07	08:34	66.6	68	62.5
31-May-07	08:39	64.7	66.5	62.5
31-May-07	08:44	64.6	66	62
31-May-07	08:49	65.4	67.5	62.5
31-May-07	08:54	64.9	66	63
31-May-07	08:59	64.7	66	62
31-May-07	09:04	65	66.5	62.5
31-May-07	09:09	66.4	67.5	64.5
31-May-07	09:14	64.5	66	62.5
31-May-07	09:19	65.8	67	63.5
31-May-07	09:24	65.8	67.5	63.5
31-May-07	09:29	65.4	67	63
31-May-07	09:34	65.1	67.5	61.5
31-May-07	09:39	64.4	66.5	61
31-May-07	09:44	63.8	66.5	60
31-May-07	09:49	62.3	64	59.5
31-May-07	09:54	65.2	66.5	62.5
31-May-07	09:59	64.3	66.5	61.5
31-May-07	10:04	63.7	65.5	60.5
31-May-07	10:09	64.7	66.5	62
31-May-07	10:14	63.8	66	61
31-May-07	10:19	64.1	65.5	62
31-May-07	10:24	65.1	66.5	62.5
31-May-07	10:29	64.7	67	62
31-May-07	10:34	64.8	67	62
31-May-07	10:39	66.6	68.5	63
31-May-07	10:44	67.7	69.5	62.5
31-May-07	10:49	62.9	65	60.5
31-May-07	10:54	65.1	67	61.5
31-May-07	10:59	65	66.5	62
31-May-07	11:04	64.9	67	61.5
31-May-07	11:09	65.4	66.5	63.5
31-May-07	11:14	64.9	66.5	62
31-May-07	11:19	68.2	72.5	62
31-May-07	11:24	70.9	74	67.5
31-May-07	11:29	69.3	71	67.5
31-May-07	11:34	68.7	71	66.5
31-May-07	11:39	68.7	70	67
31-May-07	11:44	67.8	69.5	66
31-May-07	11:49	68	70	64.5
31-May-07	11:54	65.3	67	63.5
31-May-07	11:59	62	64	59.5
31-May-07	12:04	62	64	56.5

30-Minute Measurements		
Date	Time	Leq

Date	Time	5-Minute Measurements		
		Leq	L10	L90
31-May-07	12:09	61.1	64	57.5
31-May-07	12:14	61.8	64	59
31-May-07	12:19	59.7	61	57
31-May-07	12:24	63	65.5	57.5
31-May-07	12:29	63.2	65.5	59.5
31-May-07	12:34	60.6	62.5	58.5
31-May-07	12:39	62.4	65	58
31-May-07	12:44	60.5	62.5	57.5
31-May-07	12:49	61.1	63.5	57.5
31-May-07	12:54	64.4	66	61.5
31-May-07	12:59	62.4	65	57
31-May-07	13:04	63.2	64	61
31-May-07	13:09	64	66	59.5
31-May-07	13:14	64.9	67	61.5
31-May-07	13:19	63.7	65	62
31-May-07	13:24	66.1	67	64.5
31-May-07	13:29	64.8	66.5	60.5
31-May-07	13:34	67.1	68	65.5
31-May-07	13:39	67.8	68.5	66.5
31-May-07	13:44	67.6	68.5	66
31-May-07	13:49	67.1	67.5	66
31-May-07	13:54	68.4	69.5	67
31-May-07	13:59	68.6	69.5	67
31-May-07	14:04	70.7	72.5	68
31-May-07	14:09	70.2	73	64.5
31-May-07	14:14	65.1	67	62.5
31-May-07	14:19	74.2	76.5	65
31-May-07	14:24	74.2	76	65.5
31-May-07	14:29	66.1	68	63.5
31-May-07	14:34	65.4	67.5	62.5
31-May-07	14:39	64.8	67.5	61
31-May-07	14:44	68.8	70	67.5
31-May-07	14:49	70.5	72	68.5
31-May-07	14:54	69.2	71	66
31-May-07	14:59	67.9	70	65.5
31-May-07	15:04	65.8	67	64
31-May-07	15:09	66	67	64
31-May-07	15:14	65.4	67	64
31-May-07	15:19	66.1	67.5	64
31-May-07	15:24	64.4	65	63.5
31-May-07	15:29	64.6	66.5	62
31-May-07	15:34	66.1	69	63.5
31-May-07	15:39	71.8	72.5	71
31-May-07	15:44	72	72.5	71
31-May-07	15:49	69	72	61
31-May-07	15:54	62.5	63.5	61
31-May-07	15:59	64.7	66.5	62
31-May-07	16:04	65.1	67	62.5
31-May-07	16:09	64.4	66	61.5
31-May-07	16:14	63	65	61
31-May-07	16:19	62.2	64	59.5
31-May-07	16:24	60.5	61.5	58.5
31-May-07	16:29	66.2	69	58.5
31-May-07	16:34	64.4	67	59.5
31-May-07	16:39	63.6	66	59.5
31-May-07	16:44	65.7	69	61
31-May-07	16:49	68.1	70	65.5
31-May-07	16:54	65.4	66.5	63
31-May-07	16:59	65.5	67	63.5
31-May-07	17:04	65.3	67.5	62
31-May-07	17:09	<b>76</b>	78.5	71
31-May-07	17:14	<b>75</b>	78	71
31-May-07	17:19	69	72	64
31-May-07	17:24	65.3	66.5	63
31-May-07	17:29	64.4	66	62
31-May-07	17:34	63.4	64.5	61
31-May-07	17:39	63.4	65	61.5
31-May-07	17:44	63.3	65	61
31-May-07	17:49	63.8	66	61
31-May-07	17:54	63.8	65	62
31-May-07	17:59	63.2	64.5	61
31-May-07	18:04	64.1	66	62.5
31-May-07	18:09	63.1	64	61
31-May-07	18:14	62.1	63.5	59.5
31-May-07	18:19	63.8	66	61

30-Minute Measurements		
Date	Time	Leq

Date	Time	5-Minute Measurements		
		Leq	L10	L90
31-May-07	18:24	64.1	66.5	60
31-May-07	18:29	63.6	65.5	58
31-May-07	18:34	62.8	64	60.5
31-May-07	18:39	62.7	65	59.5
31-May-07	18:44	61.6	63.5	58.5
31-May-07	18:49	64.2	67	60
31-May-07	18:54	62.4	65	56.5
31-May-07	18:59	61.3	64	57
31-May-07	19:04	59.6	62	57
31-May-07	19:09	61.4	64.5	56.5
31-May-07	19:14	59.9	62.5	56
31-May-07	19:19	62	64	57.5
31-May-07	19:24	64.1	65.5	62
31-May-07	19:29	62.3	65.5	56
31-May-07	19:34	62.7	64.5	59.5
31-May-07	19:39	60.9	63	57
31-May-07	19:44	62.2	64	56
31-May-07	19:49	62.1	64.5	57.5
31-May-07	19:54	63.7	64.5	62
31-May-07	19:59	62.3	65	59.5
31-May-07	20:04	62.2	64	55.5
31-May-07	20:09	59.2	60.5	57
31-May-07	20:14	59.1	61	56
31-May-07	20:19	60	62.5	56.5
31-May-07	20:24	63.2	64	62
31-May-07	20:29	59.8	63	56
31-May-07	20:34	57.1	58.5	55
31-May-07	20:39	57.3	59	55
31-May-07	20:44	57.2	58.5	55.5
31-May-07	20:49	57.8	59	55
31-May-07	20:54	62.3	64	56.5
31-May-07	20:59	59.1	62	55.5
31-May-07	21:04	58.1	59.5	55.5
31-May-07	21:09	58.6	59.5	55.5
31-May-07	21:14	58.1	59.5	55.5
31-May-07	21:19	58.7	61.5	55
31-May-07	21:24	59.9	62.5	56
31-May-07	21:29	58.4	60	55.5
31-May-07	21:34	56.8	58	55.5
31-May-07	21:39	57.1	58.5	55.5
31-May-07	21:44	57.3	58.5	55
31-May-07	21:49	57.1	59	54
31-May-07	21:54	56.2	57.5	54.5
31-May-07	21:59	58	59	55.5
31-May-07	22:04	57.3	59	54
31-May-07	22:09	55.3	56.5	54
31-May-07	22:14	55.1	56	54
31-May-07	22:19	55.7	57	54
31-May-07	22:24	54.6	55.5	53.5
31-May-07	22:29	54.6	55.5	53.5
31-May-07	22:34	54.6	55.5	53
31-May-07	22:39	54.3	55	53.5
31-May-07	22:44	54.8	55.5	53.5
31-May-07	22:49	55.2	56	54
31-May-07	22:54	55.7	55.5	53
31-May-07	22:59	55.5	57	53.5
31-May-07	23:04	53.5	54	52.5
31-May-07	23:09	53.5	54	52
31-May-07	23:14	53.9	55	52.5
31-May-07	23:19	53.9	55	52.5
31-May-07	23:24	52.8	53.5	52
31-May-07	23:29	53.5	54.5	52
31-May-07	23:34	52.9	54	51.5
31-May-07	23:39	68.2	65	52.5
31-May-07	23:44	54.6	56.5	52
31-May-07	23:49	54.7	55.5	52.5
31-May-07	23:54	54.6	55.5	52
31-May-07	23:59	52.8	53.5	51.5

30-Minute Measurements		
Date	Time	Leq