

**Central Reclamation Phase III
Continuous Noise Monitoring Result - City Hall**

Weather Condition:

Date	Time	5-Minute Measurements		
		Leq	L10	L90
31/03/2008	00:04:30	50.8	51	50
31/03/2008	00:09:30	51	51.5	50
31/03/2008	00:14:30	51.9	52.5	51
31/03/2008	00:19:30	51.1	51.5	50
31/03/2008	00:24:30	50.7	51.5	50
31/03/2008	00:29:30	51.1	51.5	50.5
31/03/2008	00:34:30	50.9	51.5	50.5
31/03/2008	00:39:30	50.8	51	50
31/03/2008	00:44:30	50.2	51	49
31/03/2008	00:49:30	49.6	50	49
31/03/2008	00:54:30	49.6	50	49
31/03/2008	00:59:30	49.7	50	49
31/03/2008	01:04:30	49.7	50	49
31/03/2008	01:09:30	49.4	50	48.5
31/03/2008	01:14:30	49.7	50.5	49
31/03/2008	01:19:30	49.2	49.5	48.5
31/03/2008	01:24:30	49	49.5	48.5
31/03/2008	01:29:30	48.8	49	48
31/03/2008	01:34:30	49.1	49.5	48.5
31/03/2008	01:39:30	50.2	50.5	49.5
31/03/2008	01:44:30	50.1	50.5	49.5
31/03/2008	01:49:30	50	50.5	49.5
31/03/2008	01:54:30	49.3	50	48
31/03/2008	01:59:30	48.7	49	48
31/03/2008	02:04:30	50.2	50.5	49.5
31/03/2008	02:09:30	50.5	51	49.5
31/03/2008	02:14:30	51.4	52.5	50
31/03/2008	02:19:30	49.1	50	48
31/03/2008	02:24:30	49.1	49.5	48.5
31/03/2008	02:29:30	49	49.5	48.5
31/03/2008	02:34:30	48.6	49	47.5
31/03/2008	02:39:30	48.6	49	48
31/03/2008	02:44:30	48.7	49	48
31/03/2008	02:49:30	48.9	49.5	48
31/03/2008	02:54:30	49	49.5	48
31/03/2008	02:59:30	49.1	49.5	48.5
31/03/2008	03:04:30	49.3	49.5	48.5
31/03/2008	03:09:30	50.4	51	49.5
31/03/2008	03:14:30	50.2	50.5	49.5
31/03/2008	03:19:30	50.6	51.5	49.5
31/03/2008	03:24:30	50.2	50.5	49.5
31/03/2008	03:29:30	49.1	50	48
31/03/2008	03:34:30	48.7	49	48
31/03/2008	03:39:30	49.5	50	48.5
31/03/2008	03:44:30	49.3	49.5	48.5
31/03/2008	03:49:30	49.1	49.5	48.5
31/03/2008	03:54:30	49	49.5	48
31/03/2008	03:59:30	49.3	50	48.5
31/03/2008	04:04:30	50.1	51	49
31/03/2008	04:09:30	50	50.5	49.5
31/03/2008	04:14:30	50.2	50.5	49
31/03/2008	04:19:30	49.8	50.5	49
31/03/2008	04:24:30	49.9	50.5	49
31/03/2008	04:29:30	50.5	51	49.5
31/03/2008	04:34:30	51	51.5	50
31/03/2008	04:39:30	50.9	51.5	50
31/03/2008	04:44:30	51.1	51.5	50.5
31/03/2008	04:49:30	50.8	51.5	49.5
31/03/2008	04:54:30	50.2	51	49
31/03/2008	04:59:30	50.3	51	49.5
31/03/2008	05:04:30	50.8	51.5	49.5
31/03/2008	05:09:30	51.1	51.5	50
31/03/2008	05:14:30	50.7	51	50
31/03/2008	05:19:30	50.1	50.5	49.5
31/03/2008	05:24:30	50.4	51	49.5
31/03/2008	05:29:30	50.9	51.5	49.5
31/03/2008	05:34:30	51	51.5	50
31/03/2008	05:39:30	50.9	51.5	50
31/03/2008	05:44:30	50.6	51	50
31/03/2008	05:49:30	51	51.5	50

30-Minute Measurements		
Date	Time	Leq
31-Mar-08	00:29	50.4
31-Mar-08	00:59	49.5
31-Mar-08	01:29	49.6
31-Mar-08	01:59	49.9
31-Mar-08	02:29	48.8
31-Mar-08	02:59	50.0
31-Mar-08	03:29	49.1
31-Mar-08	03:59	49.9
31-Mar-08	04:29	50.8
31-Mar-08	04:59	50.6
31-Mar-08	05:29	51.2
31-Mar-08	05:59	52.8
31-Mar-08	06:29	55.0
31-Mar-08	06:59	56.1
31-Mar-08	07:29	58.6
31-Mar-08	07:59	58.6
31-Mar-08	08:29	60.1
31-Mar-08	08:59	62.8
31-Mar-08	09:29	60.9
31-Mar-08	09:59	60.5
31-Mar-08	10:29	61.0
31-Mar-08	10:59	59.7
31-Mar-08	11:29	59.2
31-Mar-08	11:59	58.8
31-Mar-08	12:29	57.9
31-Mar-08	12:59	58.0
31-Mar-08	13:29	60.3
31-Mar-08	13:59	59.6
31-Mar-08	14:29	60.5
31-Mar-08	14:59	62.2
31-Mar-08	15:29	61.9
31-Mar-08	15:45	61.8
31-Mar-08	16:15	62.4
31-Mar-08	16:45	65.0
31-Mar-08	17:15	65.2
31-Mar-08	17:45	63.8
31-Mar-08	18:15	61.4
31-Mar-08	18:45	60.6
31-Mar-08	19:15	60.3
31-Mar-08	19:45	63.9
31-Mar-08	20:15	63.2
31-Mar-08	20:45	64.0
31-Mar-08	21:15	63.0
31-Mar-08	21:45	59.6
31-Mar-08	22:15	58.5
31-Mar-08	22:45	57.2
31-Mar-08	23:15	55.1
31-Mar-08	23:45	54.0

Date	Time	5-Minute Measurements		
		Leq	L10	L90
31/03/2008	05:54:30	52.4	53.5	51
31/03/2008	05:59:30	51.9	52.5	51
31/03/2008	06:04:30	53.4	54.5	52
31/03/2008	06:09:30	52.3	53	51.5
31/03/2008	06:14:30	52.5	53	51.5
31/03/2008	06:19:30	53.1	53.5	52.5
31/03/2008	06:24:30	53.4	54	52.5
31/03/2008	06:29:30	54.4	54.5	52.5
31/03/2008	06:34:30	55.8	58.5	53
31/03/2008	06:39:30	55	55.5	52.5
31/03/2008	06:44:30	54	55.5	52.5
31/03/2008	06:49:30	55.6	56.5	53
31/03/2008	06:54:30	55.1	56.5	53
31/03/2008	06:59:30	55	56	53.5
31/03/2008	07:04:30	55.4	56.5	53.5
31/03/2008	07:09:30	56.5	59	54
31/03/2008	07:14:30	57	58.5	55
31/03/2008	07:19:30	56.1	57.5	54.5
31/03/2008	07:24:30	56.2	57.5	54.5
31/03/2008	07:29:30	57.3	59.5	54.5
31/03/2008	07:34:30	55.7	56	54.5
31/03/2008	07:39:30	62.6	67.5	55
31/03/2008	07:44:30	58	59	55
31/03/2008	07:49:30	56.9	58.5	55
31/03/2008	07:54:30	57.3	59	55.5
31/03/2008	07:59:30	60.1	63.5	55.5
31/03/2008	08:04:30	56.4	57	55.5
31/03/2008	08:09:30	60.2	62.5	56.5
31/03/2008	08:14:30	57.9	59	56.5
31/03/2008	08:19:30	57.5	58	56.5
31/03/2008	08:24:30	58.2	59.5	56.5
31/03/2008	08:29:30	59.6	60.5	57
31/03/2008	08:34:30	59.3	60.5	57
31/03/2008	08:39:30	60.8	63.5	57
31/03/2008	08:44:30	59.4	60.5	57
31/03/2008	08:49:30	59.4	61	57
31/03/2008	08:54:30	61.7	64	58.5
31/03/2008	08:59:30	61.6	63.5	58
31/03/2008	09:04:30	63.7	67	58.5
31/03/2008	09:09:30	64.6	66.5	61.5
31/03/2008	09:14:30	61.9	63	58.5
31/03/2008	09:19:30	62	63.5	60
31/03/2008	09:24:30	62.3	64	60.5
31/03/2008	09:29:30	60.7	62	58.5
31/03/2008	09:34:30	59.9	61	58.5
31/03/2008	09:39:30	61	63	58.5
31/03/2008	09:44:30	61.3	64	57
31/03/2008	09:49:30	60.3	62.5	57.5
31/03/2008	09:54:30	61.9	64.5	58
31/03/2008	09:59:30	59.3	60.5	57.5
31/03/2008	10:04:30	59.7	61.5	57.5
31/03/2008	10:09:30	61.9	64	58.5
31/03/2008	10:14:30	59.9	61.5	57.5
31/03/2008	10:19:30	60.2	62	58
31/03/2008	10:24:30	61.6	64	58.5
31/03/2008	10:29:30	64.1	67.5	58
31/03/2008	10:34:30	60.9	63	58.5
31/03/2008	10:39:30	61.6	64	59
31/03/2008	10:44:30	58.3	59.5	57
31/03/2008	10:49:30	60.3	61.5	56.5
31/03/2008	10:54:30	58.1	59.5	56.5
31/03/2008	10:59:30	59.6	62	56.5
31/03/2008	11:04:30	57.9	59	56.5
31/03/2008	11:09:30	58.7	60	57
31/03/2008	11:14:30	58.6	59.5	57
31/03/2008	11:19:30	61.1	64	57
31/03/2008	11:24:30	61.2	63.5	56.5
31/03/2008	11:29:30	58.3	59.5	56.5
31/03/2008	11:34:30	57.7	58.5	56.5
31/03/2008	11:39:30	57.8	59	56.5
31/03/2008	11:44:30	57.6	58.5	55.5
31/03/2008	11:49:30	60.4	62.5	56
31/03/2008	11:54:30	61.7	63	56.5
31/03/2008	11:59:30	58.6	60.5	55.5
31/03/2008	12:04:30	58.4	60	56.5

30-Minute Measurements		
Date	Time	Leq

Date	Time	5-Minute Measurements		
		Leq	L10	L90
31/03/2008	12:09:30	58.8	60.5	56
31/03/2008	12:14:30	57.5	59	55.5
31/03/2008	12:19:30	59.3	60.5	56
31/03/2008	12:24:30	59.9	62.5	56
31/03/2008	12:29:30	56.8	57.5	55.5
31/03/2008	12:34:30	57.2	58.5	55.5
31/03/2008	12:39:30	56.2	57	55
31/03/2008	12:44:30	56.6	57.5	55
31/03/2008	12:49:30	56.7	57.5	55
31/03/2008	12:54:30	61.3	63	56
31/03/2008	12:59:30	56.3	57	55
31/03/2008	13:04:30	56.4	57.5	55
31/03/2008	13:09:30	56.6	58	55
31/03/2008	13:14:30	56.2	57	55
31/03/2008	13:19:30	57.9	58.5	55.5
31/03/2008	13:24:30	61.6	63.5	58.5
31/03/2008	13:29:30	59.7	62	56.5
31/03/2008	13:34:30	58.9	60.5	56.5
31/03/2008	13:39:30	59.1	61	56.5
31/03/2008	13:44:30	60.2	62	57.5
31/03/2008	13:49:30	60.6	63.5	57
31/03/2008	13:54:30	62.5	64.5	58.5
31/03/2008	13:59:30	60	61.5	57.5
31/03/2008	14:04:30	60.1	62.5	57
31/03/2008	14:09:30	59.4	61.5	57
31/03/2008	14:14:30	59.2	60.5	57
31/03/2008	14:19:30	59.2	61	57
31/03/2008	14:24:30	59.5	62	56.5
31/03/2008	14:29:30	60.6	62	57.5
31/03/2008	14:34:30	59.5	61	57.5
31/03/2008	14:39:30	60.7	62	58.5
31/03/2008	14:44:30	60.2	61.5	58
31/03/2008	14:49:30	59.8	61.5	57.5
31/03/2008	14:54:30	61.7	63.5	59
31/03/2008	14:59:30	62.2	64	59.5
31/03/2008	15:04:30	61.3	62	60
31/03/2008	15:09:30	61.9	63.5	60
31/03/2008	15:14:30	62	63	60
31/03/2008	15:19:30	62.1	63	60.5
31/03/2008	15:24:30	63.4	65	61
31/03/2008	15:29:30	62.1	63	60.5
31/03/2008	15:34:30	61.6	62.5	59.5
31/03/2008	15:45:14	60.9	62	58.5
31/03/2008	15:50:14	61.3	62	59.5
31/03/2008	15:55:14	62.9	65.5	60
31/03/2008	16:00:14	62	63	60.5
31/03/2008	16:05:14	61.7	63	59.5
31/03/2008	16:10:14	61.6	63	59
31/03/2008	16:15:14	60.9	62.5	58.5
31/03/2008	16:20:14	60.9	63.5	58.5
31/03/2008	16:25:14	61.7	63.5	59
31/03/2008	16:30:14	63.6	66	60
31/03/2008	16:35:14	62.3	64	59.5
31/03/2008	16:40:14	64.1	66.5	60.5
31/03/2008	16:45:14	64.1	66	61
31/03/2008	16:50:14	62.5	64	59.5
31/03/2008	16:55:14	65.5	67	62
31/03/2008	17:00:14	65.4	66.5	64
31/03/2008	17:05:14	65.7	67	64
31/03/2008	17:10:14	65.8	67	64
31/03/2008	17:15:14	65.3	66.5	63.5
31/03/2008	17:20:14	65.1	66	64
31/03/2008	17:25:14	65.1	66	63.5
31/03/2008	17:30:14	64.6	65.5	62.5
31/03/2008	17:35:14	64.9	66	63.5
31/03/2008	17:40:14	66	67	64.5
31/03/2008	17:45:14	65.2	66.5	63.5
31/03/2008	17:50:14	65.3	66	64
31/03/2008	17:55:14	63.6	65	61
31/03/2008	18:00:14	62.6	64	61
31/03/2008	18:05:14	61.9	63.5	59
31/03/2008	18:10:14	63.4	65	60.5
31/03/2008	18:15:14	61.2	62.5	59.5
31/03/2008	18:20:14	61.5	62.5	59.5
31/03/2008	18:25:14	63	65	60.5

30-Minute Measurements		
Date	Time	Leq

Date	Time	5-Minute Measurements		
		Leq	L10	L90
31/03/2008	18:30:14	61.1	62	59
31/03/2008	18:35:14	60.8	62	59.5
31/03/2008	18:40:14	60.5	61.5	59
31/03/2008	18:45:14	60.1	61	59
31/03/2008	18:50:14	61	62	59
31/03/2008	18:55:14	59.9	61	57.5
31/03/2008	19:00:14	61.4	64	58
31/03/2008	19:05:14	59.9	62.5	57
31/03/2008	19:10:14	60.9	63	58
31/03/2008	19:15:14	60	61.5	57
31/03/2008	19:20:14	59	60.5	56.5
31/03/2008	19:25:14	60.6	63	57.5
31/03/2008	19:30:14	61.6	64	57.5
31/03/2008	19:35:14	60.5	62	58
31/03/2008	19:40:14	59.6	61.5	57
31/03/2008	19:45:14	64.6	64.5	58.5
31/03/2008	19:50:14	61.5	62.5	59.5
31/03/2008	19:55:14	65.2	65.5	60
31/03/2008	20:00:14	65	66.5	61.5
31/03/2008	20:05:14	62.8	65	59
31/03/2008	20:10:14	63.1	64	59.5
31/03/2008	20:15:14	61.6	63	59.5
31/03/2008	20:20:14	61.4	63	59
31/03/2008	20:25:14	63.5	64.5	62
31/03/2008	20:30:14	63.9	65	62.5
31/03/2008	20:35:14	64	65	62.5
31/03/2008	20:40:14	63.8	65	62.5
31/03/2008	20:45:14	63.7	65	62
31/03/2008	20:50:14	63.2	64	62
31/03/2008	20:55:14	63.7	65.5	60
31/03/2008	21:00:14	64	65.5	61.5
31/03/2008	21:05:14	64.5	65.5	63
31/03/2008	21:10:14	64.5	65	63.5
31/03/2008	21:15:14	64.7	65.5	63.5
31/03/2008	21:20:14	64.8	65.5	63.5
31/03/2008	21:25:14	63.9	65.5	60
31/03/2008	21:30:14	61.2	63	58.5
31/03/2008	21:35:14	60.5	62.5	57.5
31/03/2008	21:40:14	60.8	62.5	57.5
31/03/2008	21:45:14	59.8	61.5	57.5
31/03/2008	21:50:14	59.7	61.5	56.5
31/03/2008	21:55:14	59.9	62	56.5
31/03/2008	22:00:14	60.2	62	56.5
31/03/2008	22:05:14	59.7	61.5	56.5
31/03/2008	22:10:14	58.2	60	55.5
31/03/2008	22:15:14	57.6	59	55.5
31/03/2008	22:20:14	58.2	59	55.5
31/03/2008	22:25:14	58.8	60.5	56
31/03/2008	22:30:14	58.6	60.5	56
31/03/2008	22:35:14	58.7	60	56.5
31/03/2008	22:40:14	58.7	60	57
31/03/2008	22:45:14	58.3	60.5	55.5
31/03/2008	22:50:14	57.3	59	55
31/03/2008	22:55:14	58.6	60.5	55.5
31/03/2008	23:00:14	56.7	58.5	54.5
31/03/2008	23:05:14	54.7	55	53.5
31/03/2008	23:10:14	56.2	58	54
31/03/2008	23:15:14	55.2	56	54
31/03/2008	23:20:14	57	57.5	54.5
31/03/2008	23:25:14	54.6	55	54
31/03/2008	23:30:14	55	56	53.5
31/03/2008	23:35:14	54.3	54.5	53.5
31/03/2008	23:40:14	53.9	54	53
31/03/2008	23:45:14	54.2	54.5	53.5
31/03/2008	23:50:14	53.9	54.5	53
31/03/2008	23:55:14	54.1	54.5	53.5

30-Minute Measurements		
Date	Time	Leq