



Central Reclamation Phase III Design and Construction for the Minimum Option

IEC Inspection Report

EP-122/2002

13 November 2003

Details of Inspection:

Date/Time: 13 November 2003 9:15AM-11:45AM
Locations: Central Reclamation Phase III, Pier No. 7, IRAE barge, and the chemical store at CR4

Observations on ET Inspection:

ET Inspection carried out in accordance with EM and A Manual and EP requirements	Yes/No*
* If No, details provided below:	

ET Inspection Report:

Report No. 17	
Date of Issue: 17 November 2003	
IEC confirms findings of ET Inspection Report	Yes/No*
* If No, details provided below:	
Additional observations:	
<ol style="list-style-type: none"> 1) Oil and grease under the crane at on the dredging barge, contractor requested to clean this up. 2) Additional Silt screen between barge and silt curtain frame required lifting. 3) Helipad location – unpaved areas dusty, contractor requested to water these. 	

Signed:

Bill Douglas IEC



Central Reclamation Phase III Design and Construction for the Minimum Option

IEC Inspection Report

EP-122/2002

10 December 2003

Details of Inspection:

Date/Time: 10 December 2003 9:00AM-11:00AM
Locations: Central Reclamation Phase III, Pier No. 7, IRAE barge, SI Barge, chemical store at CR4

Observations on ET Inspection:

ET Inspection carried out in accordance with EM and A Manual and EP requirements	Yes/No*
* If No, details provided below:	

ET Inspection Report:

Report No. 22	
Date of Issue: 10 December 2003	
IEC confirms findings of ET Inspection Report	Yes/No*
* If No, details provided below:	

Signed:

Bill Douglas IEC



Central Reclamation Phase III Design and Construction for the Minimum Option

IEC Inspection Report EP-122/2002

10 December 2003

Details of Inspection:

Date/Time: 10 December 11:00-12:15AM
Locations: City Hall location of Dust and Noise Meters, M11, M2, M3

Observations on ET Monitoring:

Monitoring in accordance with EM and A Manual and EP requirements	Yes/No*
<p>* If No, details provided below:</p> <p>Comments:</p> <p>Noise monitor operating correctly in accordance with EP. Dust monitor not yet operating Water Quality monitoring carried out in accordance with EP.</p>	

Signed:

Bill Douglas IEC



Central Reclamation Phase III Design and Construction for the Minimum Option

IEC Inspection Report EP-122/2002 14 January 2004

Details of Inspection:

Date/Time: 14 January 2004 9:00AM-12:00AM
Locations: Central Reclamation Phase III, Pier No. 7, IRAE barge, SI Barge, chemical store at CR4, GPO walkway, Wanchai helipad

Observations on ET Inspection:

ET Inspection carried out in accordance with EM and A Manual and EP requirements	Yes/No*
* If No, details provided below:	

ET Inspection Report:

Report No. 27	
Date of Issue: 14 January 2004	
IEC confirms findings of ET Inspection Report	Yes/No*
* If No, details provided below:	

Signed:

Bill Douglas IEC



Central Reclamation Phase III IEC

Central Reclamation Phase III Design and Construction for the Minimum Option

IEC Inspection Report EP-122/2002 14 January 2004

Details of Inspection:

Date/Time: 14 January 2004 11:30-12:00AM

Locations: City Hall location of Dust and Noise Meters, M3

Observations on ET Monitoring:

Monitoring in accordance with EM and A Manual and EP requirements	Yes/No*
<p>* If No, details provided below:</p> <p>Comments:</p> <p>Noise monitor operating correctly in accordance with EP. Dust monitor not yet operating Water Quality monitoring carried out in accordance with EP.</p>	

Signed:

Bill Douglas IEC