

**Central Reclamation Phase III
TSP Monitoring Result**

STATION	Date	Weather Condition	24-hour TSP conc., $\mu\text{g}/\text{m}^3$	Date	1-hour TSP conc., $\mu\text{g}/\text{m}^3$	Time	
PLA	03-Jan-06	Fine	93	3-Jan-06	38720	9:29	10:29
					305	10:29	11:29
					337	11:29	12:29
City Hall	-	-	-		-	-	-
					-	-	-
					-	-	-

STATION	Date	Weather Condition	24-hour TSP conc., $\mu\text{g}/\text{m}^3$	Date	1-hour TSP conc., $\mu\text{g}/\text{m}^3$	Time	
PLA	09-Jan-06	Fine	130	09-Jan-06	99	9:31	10:31
					99	10:31	11:31
					105	11:31	12:31
City Hall	-	-	-		-	-	-
					-	-	-
					-	-	-

STATION	Date	Weather Condition	24-hour TSP conc., $\mu\text{g}/\text{m}^3$	Date	1-hour TSP conc., $\mu\text{g}/\text{m}^3$	Time	
PLA	12-Jan-06	Fine	141	12-Jan-06	112	09:33	10:33
					103	10:33	11:33
					122	11:33	12:33
City Hall	-	-	-		-	-	-
					-	-	-
					-	-	-

STATION	Date	Weather Condition	24-hour TSP conc., $\mu\text{g}/\text{m}^3$	Date	1-hour TSP conc., $\mu\text{g}/\text{m}^3$	Time	
PLA	18-Jan-06	Fine	70	18-Jan-06	101	10:03	11:03
					129	12:01	13:01
					158	13:01	13:29
City Hall	-	-	-		-	-	-
					-	-	-
					-	-	-

Note: Meter power down resulted in partial loss of data.

STATION	Date	Weather Condition	24-hour TSP conc., $\mu\text{g}/\text{m}^3$	Date	1-hour TSP conc., $\mu\text{g}/\text{m}^3$	Time	
PLA	26-Jan-06	Fine	128	26-Jan-06	64	09:04	10:04
					53	10:04	11:04
					51	11:04	12:04
City Hall	-	-	-		-	-	-
					-	-	-
					-	-	-

General Remarks:

Monitoring was not conducted at the City Hall monitoring station because exterior renovation works were undertaken by City Hall at the elevated walkway area.